



MEASURE YOUR HEAD

Determine the circumference of the widest part of your head by using a flexible tape measure. Generally, the widest part of a person's head is the area 2.5cm (1") above the eyebrows and ears. However, we suggest measuring a few spots above and below that area to determine the greatest measurement before referring to our size tables. We also suggest testing the fit of a helmet one size smaller and one size larger than what the chart recommends. No helmet can provide protection if it's too uncomfortable to wear.



SIZE	YS	YM	YL	XS
U.S.HAT SIZE	5 7/8 - 6	6 1/8 - 6 1/4	6 3/8 - 6 1/2	6 5/8 - 6 3/4
INCHES	18.25 - 19.00	19.00 - 19.75	19.75 - 20.5	20.5 - 21.25
CM	47 - 48	49 - 50	51 - 52	53 - 54

SIZE	S	M	L	X
U.S.HAT SIZE	6 7/8 - 7	7 1/8 - 7 1/4	7 3/8 - 7 1/2	7 5/8 - 7 3/4
INCHES	21.25 - 22.00	22.00 - 23.00	23.00 - 23.75	24.00 - 24.50
CM	55 - 56	57 - 58	59 - 60	61 - 62

SIZE	2X	3X	4X	5X
U.S.HAT SIZE	7 7/8 - 8	8 1/8 - 8 1/4	8 3/8 - 8 1/2	8 5/8 - 8 3/4
INCHES	24.50 - 25.25	25.25 - 26.00	26.00 - 26.75	26.75 - 27.50
CM	63 - 64	65 - 66	67 - 68	69 - 70